

TeePeeTM

DWV Test Tool



Easy to Use

- Installs quickly – No air pump or compressor needed!
- No special fittings or tools needed
- Works with PVC/ABS or cast iron DWV systems
- No splash-out when draining

Top Performance

- Holds higher test pressures than inflatable plugs
- Heavy-duty, coated steel handle with rubber seal
- Durable and reusable

Test tool locks securely in place during test.
No air pump, no inflation – no risk of blowout or puncture.



Supply

Drainage

Support

Specialties

www.siouxchief.com

TAKE THE FIELD.



Easy to Use!

Before Each Use: Apply silicone lubricant to outside edges of rubber seal


1. Release the locking mechanism and push the curved foot up towards plug head. Insert plug head into face of tee, then orient plug to position the curved 'foot' to rest on bottom of the tee threads.
2. Push handle straight down as plug head aligns and pivots up into pipe. Push until plug is locked and head is sealed in place.

Note: Locking mechanism will click twice and rest in second notch.

Test System According to Local Codes		
Model	Size	Max Water Test Pressure
881-52	2"	65 PSI / 150 FT-HD
881-53	3"	65 PSI / 150 FT-HD
881-54	4"	44 PSI / 100 FT-HD
881-56	6"	35 PSI / 80 FT-HD

3. After test, push handle down slightly and pull back on locking mechanism to release from second notch. Lift handle until locking mechanism catches and locks in first notch. This will allow test to drain past the plug at the back of the tee.
4. After test has drained completely, release the locking mechanism from the first notch and remove plug.

After Each Use: Rinse plug with water & inspect. Store in dry area, out of sunlight



» Buying Information

ITEM NO.	DESCRIPTION	MIN. QTY.	CASE QTY.
TeePee - Mechanical Test Tool			
881-52	2" TeePee Mechanical Test Tool - for PVC, ABS or Cast Iron Test Tees	1	1
881-53	3" TeePee Mechanical Test Tool - for PVC, ABS or Cast Iron Test Tees	1	1
881-54	4" TeePee Mechanical Test Tool - for PVC, ABS or Cast Iron Test Tees	1	1
881-56	6" TeePee Mechanical Test Tool - for PVC, ABS or Cast Iron Test Tees	1	1